

Bulletin: 44-21

TO: All Greenheck Representatives
FROM: Andy Jackson, Product Manager, Louvers
DATE: September 13, 2021
SUBJECT: Select Honeywell Actuator Shortages



We are anticipating a supply chain disruption of the most popular high-torque Honeywell actuators used on our operable blade louver products. We do not know how long this disruption may last, but we are confident that it will be short-term.

It is possible that we may proactively substitute Honeywell actuators to lessen the risk of late shipments and substitute equivalent Belimo actuators on operable blade louver products. This potential substitution may impact orders currently in our backlog and/or newly placed orders. Orders requiring multiple high-torque actuators will ship with the same brand actuators. None will contain a mix of Honeywell and Belimo to maintain consistency.

The chart illustrates the current Honeywell actuators that may be impacted along with a viable Belimo substitute.

Actuator Manufacturer	Actuator Model	Greenheck Part #		Actuator Manufacturer	Actuator Model	Greenheck Part #
Honeywell	MS4120F1006	382823		Belimo	AFBUP	384376
Honeywell	MS4120F1204	383024		Belimo	AFBUP-S	384377
Honeywell	MS8120F1002	382824		Belimo	AFBUP	384376
Honeywell	MS8120F1200	383255		Belimo	AFBUP-S	384377

Please contact your regional sales customer care team if your order cannot accept a substitute actuator and must ship with the selected Honeywell. You may also contact louver customer service (louvers@greenheck.com). Please note that not allowing substitution may result in late shipments or longer lead times.

Thank you in advance for your understanding.